

EXTENT OF DAMAGE

Loss of form 1 (slight, thin-layered)

definition


Loss of form 1 is a slight, thin-layered loss zone near to the surface. The loss of form starts, where the original surface conditioning is not longer visible.

foto



data file: ALX_08.jpg

symbol of mapping




EXTENT OF DAMAGE

Loss of form 3 (fragmentary from 50% loss)

definition


Loss of form 3 describes losses, which contribute to indistinctness of form and design. This applies to visible surfaces an complete workpieces or sculptures. The fragmenting of the entire surface, workpiece or sculpture is > 50 %.

foto



data file: lossform.jpg

symbol of mapping




EXTENT OF DAMAGE

Loss of form 4 (unrecognizable state)

definition

Loss of form 4 is the loss, where the fragmenting of the surface, the workpiece or the sculpture has so far advanced, that the original form and design is indistinct.

foto



data file: lossform.jpg

symbol of mapping

